

sagemax.com

sagemax[®]



Sagemax experience

NexxZr⁺ white
monolithic
by Dr. Gonzalo Perea

NexxZr⁺ white monolithic
by Dr. Gonzalo Perea

Sagemax experience

Initial situation and preparation



The patient came to us with a faulty treatment. The inserted acrylic crowns had a poor anatomical fit, resulting in leaking margins, tartar, caries and severe halitosis.



In the first step, the acrylic crowns were removed.




Tartar and discoloration were then removed, and the tooth surfaces were prepared, polished and smoothed.


Design and try-in



Digital design in exocad (Co. exocad) after digital scanning.



Occlusal view of the 3D design of the anatomically designed crowns in the upper jaw.



Occlusal view of the 3D design of the anatomically designed crowns in the lower jaw.



Try-in and design check with milled acrylic crowns.

Crown fabrication and cementation



The crowns were fabricated from NexxZr+ white zirconia and subsequently stained and glazed with IPS Ivoclar (Co. Ivoclar).



Cementation of the restorations in the mouth.

Final result





The final result of the stained and glazed NexxZr⁺ white crowns after cementation. A smile that enchants.



Dental designer

Dr. Gonzalo Perea
Dentist, Mexico

 DrGonzaloPerea
 drgonzaloperea

Contact us
info@sagemax.com

sagemax.com

Follow us
[@sagemax.official](https://www.instagram.com/sagemax.official)

